
## **Smoke and Dye Testing Summary**

## **High Level Sewershed**

Run Summa	iry <del></del>						
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-225	Smoke	8/11/2009	ADS/TM	S19MM_002MH	Dry	Yes	1,037.50



## **Smoke and Dye Testing Summary**

## **High Level Sewershed**

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-225	Smoke	8/11/2009	ADS/TM	S19MM_002MH	Dry	Yes	1,037.50

ated Pipes ====				
Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S19MM_013G1	S19MM_013MH	S19MM_021MH	254.986	10
S19MM_005G1	S19MM_005MH	S19MM_022MH	50.899	12
S19MM_002G1	S19MM_002MH	S19MM_030MH	292.599	12
S19MM_021G2	S19MM_021MH	S19MM_002MH	291.361	12
S19MM_030G1	S19MM_030MH	S19MM_005MH	147.652	12

**Observations & Photos**